


CORNER RECORD

Document Number APN 050-061-23

City of MILL VALLEY

County of MARIN, California

Brief Legal Description A PORTION OF LOT 19, 5 RM 10, SUB. NO. 2, MARIN HALF ACRE HOMES



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey MARCH 30, 2007

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial


Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND 3/4" IRON PIPES AS SHOWN ON 19 OS 65 AND ON REVERSE.

A description of the physical condition of the monument as found and as set or reset: _____
SET 2"x2" HUBS WITH TACK FOR PROPOSED GARAGE CORNER AND WITH TAG FOR PROPERTY
LINE POINT AS SHOWN ON REVERSE.

SURVEYOR'S STATEMENT

This Corner record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on APRIL 4, 2007
Signed [Signature] P.L.S. or R.C.E. No. PLS 5296



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APRIL 10, 2007
and examined and filed MAY 15, 2007
Signed [Signature] P.L.S. or R.C.E. No. 7128
Title COUNTY SURVEYOR



County Surveyor's Comment _____