


**CORNER RECORD**

Document Number A.P. 188-140-29

City of BOLINAS

County of MARIN, California

Brief Legal Description PARCEL 2 19 P.M. 53



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 4/4/01

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND ROTTEN HUBS (SEE PAGE 2)

A description of the physical condition of the monument as found and as set or reset:

RESET HUBS WITH 3/4" PIPES AND PLUGS STAMPED  
P.L.S. 4694 (SEE PAGE 2)

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on APRIL 4, 2001

Signed Lawrence P. Doyle P.L.S or R.C.E. No. P.L.S. 4694




**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received 1-3-2002

and examined and filed 1-8-2002

Signed Craig Tackabery P.L.S or R.C.E. No. 7128

Title DEPUTY



County Surveyor's Comment \_\_\_\_\_



HORSESHOE HILL ROAD

FOUND ROTTEN HUB AND TAG L.S. 2738 PER 19 P.M. 53  
REPLACED WITH 3/4" PIPE AND PLUG L.S. 4694

PARCEL 2  
19 P.M. 53

225.38'

S 71°44'00" W  
325.41'

FOUND ROTTEN HUB AND NAIL  
REPLACED WITH 3/4" PIPE AND PLUG L.S. 4694

PARCEL 1

100.03'

FOUND 3/4"  
PIPE AND TAG L.S. 2738  
PER 19 P.M. 53

A.P. 188-140-29



CORNER RECORD

19 P.M. 53

BOLINAS MARIEN COUNTY CALIFORNIA

LAWRENCE P. DOYLE

LAND SURVEYOR/CIVIL ENGINEER  
P.O. BOX 1809 MILL VALLEY CA 94542 (415-388-9585)

SCALE 1" = 30'

DATE 4/2/01

DRAWN BY: AVB

SHEET 1

DRAWING NO. 887-00