Document Number ______A.P. _016-151-03 **CORNER RECORD** MARIN SAN RAFAEL LOT 55 PER 7 R.M. 97 Brief Legal Description COORDINATES (Optional) CORNER TYPE NAD83 🗆 NAD27 I Zone Control Government Corner NAD83 Epoch \boxtimes Elev. Meander Property NAVD88 🗖 NGVD29 🗖 Vert. Datum: Imperial □ Metric 🗆 Meas. Units: Other Rancho 8/26/10 Date of Survey Rebuilt 🔲 Reestablished 🛛 Established Found and tagged \square Left as found \square Corner-Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: REESTABLISHED THE SOUTHEASTERLY LINE OF LOT 55 USING STREET MONUMENTS ON LOCHINVAR ROAD PER 7 R.M. 97 AND AS SHOWN ON SHEET 2. SEE SHEET 2. A description of the physical condition of the monument as found and as set or reset: SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with AUGUST 30, 2010. the Land Surveyor's Act on No. 4694 COUNTY SURVEYOR'S STATEMENT SEPTEMBER 27, 2010 This Corner Record was received OCTOBER 21, 2010 and examined and filed P.L.S. or R.C.E. No. ____7128 Signed **County Surveyor's Comment**

