


CORNER RECORD

Document Number APN=22-212-15 & 25
County of MARIN, California

City of LARKSPUR

Brief Legal Description _____



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 4-13-10

COORDINATES
(Optional)

N. _____
E. _____
Zone. _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND 2 EXISTING MONUMENTS UNDISTURBED, RM 12-60
SEE SHT. 2 OF 2.

A description of the physical condition of the monument as found and as set or reset: GOOD CONDITION,
SET NAILS AND TAGS - 20' OFFSET, SEE SHT. 2 OF 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on APRIL 13 2010

Signed Arthur J. Lang L.S. or R.C.E. Number RCE 12247



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APRIL 21, 2010 and examined
and filed MAY 6, 2010

Signed [Signature] Title COUNTY SURVEYOR



County Surveyor's Comment _____

BON AIB ROAD

FOUND MONUMENT

COO. ELJ 910 DRIVE

LOT 122

FOUND MONUMENT



SCALE: 1" = 30'

113.92'
N47°30'00"W

30.00'
S42°30'00"W

R=470'
Δ=0°49'26"
L=6.76'

R=470.00'
Δ=0°26'49"
L=20.07'

FOUND HUB

R=470.00'
Δ=1°36'09"
L=10.74'

109.00'
S39°44'20"W

FOUND HUB ± NL

20' OFF-SET
SET-NAIL AND TAG

50.00'
N50°15'40"W

20.00'
S59°51'05"E

LOT 121

285.91'
N39°44'20"E

20' OFF-SET
SET-NAIL AND TAG