


# CORNER RECORD

Document Number A.P. # 24-184-16, 17 & 21

City of Corte Madera

County of Marin, California

Brief Legal Description Lot 67, Block 3 Madera Gardens Subdivision 10 (9 M 36) & Lots 68 & 72, Block 3 Madera Gardens Subdivision 9 (9 M 35)



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found the corner of the mid angle point of the Southern limit of lot 68 (9 M 35). Reestablished the rear corners of lot 67 (9 M 36) and lots 68 & 72 (9 M 35). Found Iron pipe monuments in Lakeside Drive & Steel rods at the rear of lot 68 (9 M 35) & lot 4 (8 M 92) were used to reset the record lot corners.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_  
Found street monuments were in good condition under approx. 3" AC. Found steel rods were in good condition and appeared undisturbed. Set corners were monumented w/1" Iron pipes or 1/2" rebar & plastic caps as shown on the attached exhibit.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 5 1997.

Signed [Signature] L.S. or R.C.E. Number 6951



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received August 4 1997 and examined and filed August 5, 1997.

Signed [Signature] Title Deputy



County Surveyor's Comment \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

