CORNER RECORD Document Number _____A.P.# 034-291-35 **TIBURON** City of _ County of MARIN __, California PARCEL 1, 7 P.M. 52 Brief Legal Description CORNER TYPE **COORDINATES (Optional)** Government Corner П NAD27 Control Zone NAD83 NAD83 Epoch Meander \boxtimes Property Elev. Vert. Datum: NGVD29 □ NAVD88 Rancho Other Meas. Units: Metric 🗖 Imperial 🗖 10/15/08 Date of Survey Corner-Left as found Found and tagged Established Reestablished X Rebuilt 🗌 Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: REESTABLISHED 2 CORNERS, ONE ANGLE POINT, AND ONE POINT ON PROPERTY LINE OF PARCEL 1, 7 P.M. 52 BASED UPON FOUND STREET MONUMENTS PER 7 P.M. 52. FOUND PIPE & PLUG, R.C.E. 30465 PER CORNER RECORD 034-291-35 A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on OCTOBER 15 - 2008 P.L.S. or R.C.E. No. ______P.L.S. 4694 No. 4694 Exp. 9/30/0**COUNTY SURVEYOR'S STATEMENT** CALI NOVEMBER 3,2008 This Corner Record was received DECEMBER 15, 2008 and examined and filed P.L.S. or R.C.E. No. 7128 Title COUNTY SURVEYOR **County Surveyor's Comment**

