


CORNER RECORD

Document Number 039-081-10

City of TIBURON

County of MARIN, California

Brief Legal Description Lot 1,2 OS 158, as shown on 2002 Maps 189.



CORNER TYPE

Government Corner Control
Meaneder Property
Rancho Other
Date of Survey Aug. 27, 2013

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 3/4" Iron Pipes in record position and used to reestablish the
SE Corner of Lot 1, 2 OS 158 (See map on reverse side)

A description of the physical condition of the monument as found and as set or reset: _____

Set 1/2" iron pipe LS7237 at southeast corner

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on August 28, 2013

Signed Michael E. Ford P.L.S. or R.C.E. No. 7237



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPTEMBER 4, 2013
and examined and filed OCTOBER 7, 2013

Signed Richard G. Simonitch P.L.S. or R.C.E. No. 7821

Title DEPUTY CO. SURV.



County Surveyor's Comment

