


**CORNER RECORD**

Document Number APN. 039-111-06  
City of TIBURON County of MARIN, California

Brief Legal Description LOT 6, FRANCISCO VISTA, 11 RM 43 M.C.R., TIBURON



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey \_\_\_\_\_

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner -- Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 3/4" IRON PIPE IN RECORD LOCATION PER 11 R.M. 43. USE STREET MONUMENTS AND RECORD INFORMATION TO REESTABLISH CORNERS AND PROPERTY LINE POINTS AS INDICATED, ALL PER 11 R.M. 43


A description of the physical condition of the monument as found and as set or reset:

FOUND 3/4" IRON PIPE UNDISTURBED. FOUND 1/2" IRON PIN DISTURBED WITH BASE AT RECORD LOCATION. SET 1/2" IRON PINS AT RECORD LOCATION AS INDICATED. SET CAP 'L56234'.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on AUGUST 25 2003

Signed [Signature] P.L.S or R.C.E. No. L56234



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received SEPTEMBER 3, 2003

and examined and filed SEPTEMBER 16, 2003

Signed [Signature] P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_