

# CORNER RECORD


Document Number I.N. 96-06312

City of Tiburon

County of Marin

California

Brief Legal Description Lot 3, Map of Mar View, 11-Maps-41, Marin County Records



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found 3/4" I.D. iron pipes with plastic plug "LS 3775" at the westerly and southwesterly boundary of Lot 2,  
Set 3/4" I.D. iron pipes with plastic plug "PLS 4794" at the easterly and southeasterly boundary of Lot 4,  
and at most southerly corner of Lot 3. Set redwood hub with nail & tag "LS 4794" on northeasterly and  
southwesterly line of Lot 3, Map of Mar View, recorded in Book 11 of Maps, at Page 41, Marin County Records.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_  
As shown upon reverse side.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
 the Land Surveyors' Act of \_\_\_\_\_ September 18, \_\_\_\_\_ 19 97.

Signed \_\_\_\_\_ L.S. or R.C.E. Number PLS 4794



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received October 3 19 97 and examined  
 and filed October 3 19 97.

Signed John M. Wooley Title Deputy



County Surveyor's Comment \_\_\_\_\_