


# CORNER RECORD

Document Number 39.280.15  
County of MARIN, California

City of TIBURON

Brief Legal Description LOT 10-A 24 PM 27



### CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey MAY 4, 2004

### COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Reestablish the exterior boundary for LOT 10-A, 24 PM 27 from EXISTING BRASS DISC IN NORMAN WAY (AS SHOWN UPON SAID 24 PM 27). Refer to sketch on reverse side for details.

A description of the physical condition of the monument as found and as set or reset:


set 1/2" rebar with PLS CAP 5379 AFFIXED to top & driven flush with surrounding grade. Refer to sketch for location of set points

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on MAY 21 2004

Signed Douglas J. Scranton P.L.S. or R.C.E. No. 5379



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 1, 2004

and examined and filed JUNE 22, 2004

Signed \_\_\_\_\_ P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_

Prepared by DJ SCRANTON SURVEYING, NOVATO, CA