

CORNER RECORD


A.P.N. 50-052-46

Document Number 97-000210

City of MILL VALLEY

County of MARIN, California

Brief Legal Description PARCEL DESCRIBED IN D.N. 97-000210 AND SHOWN ON A MAP FILED IN BOOK 18 AT PAGE 78 OF RECORDED MAPS.



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey _____
- Control
- Property
- Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: TWO FOUND PROPERTY CORNERS PER 18 RM. 78, FILED IN THE MARIN COUNTY RECORDER'S OFFICE, WERE FOUND, MEASURED AND USED AS THE BASIS OF BEARINGS TO REESTABLISH THE SOUTHEAST CORNER AS SHOWN ON SAID MAP

A description of the physical condition of the monument as found and as set or reset: THE CORNERS FOUND (SEE ATTACHED DIAGRAM) ARE 3/4" IRON PIPES, UNDISTURBED, AND WITHOUT MATERIAL DISCREPENCY. A 3/4" IRON PIPE WAS SET AT RECORD SOUTEAST CORNER PER 18 RM. 78.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on MARCH 30 2000.

Signed [Signature] L.S. or R.C.E. Number LS 6344



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 29, 2000 and examined and filed JULY 10, 2000.

Signed [Signature] Title DEPUTY



County Surveyor's Comment _____

