


# CORNER RECORD

Document Number 21-Maps-31

City of Vicinity Mill Valley

County of MARIN, California

Brief Legal Description Plots I-97 & I-98, 21-Maps-31, Marin County Records



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

(A) Found 3/4" I.D. iron pipe as shown upon 21-Maps-31

(B) Found 3/4" I.D. iron pipe with wood plug (tag missing)

(C) Found 1/2" rebar

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

(D) Set 3/4" I.D. galvanized iron pipe with plastic plug "PLS 4794 DANSKIN"

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 13 October 1999.


Signed [Signature] L.S. or R.C.E. Number LS 4794



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCTOBER 15 1999 and examined and filed OCTOBER 18 1999.

Signed [Signature] Title DEPUTY



County Surveyor's Comment \_\_\_\_\_