CORNER RECORD		7.F.N. 53-101-18	
City of Tiburan		umber <u>D.N 94-057148</u>	
Brief Legal Description Lot 102" Map of L	- County of _ JHD Reed	Marin , Ca	alifor
The second of th	THE NEED	TICIOTTO UNIT 4 81	$\frac{1}{1}$
CORNER TY		COORDINATES (Optional)	
Government Corner Meander	Control ☐ Property 🔀	N E	
Rancho Date of Survey	Other	Zone Datum Elev	
Corner — Left as found Found and tagged	Established [☐ Reestablished ☑ Rebuilt ☐	<u> </u>
Identification and type of corner found: Evidence used to it	dentify or procedure	used to establish or reestablish the co	
			mei
Found standard well me	onu ments	in Position pe	r
8 RM 56. Set propert	y corner	s as shown on	
sheet two.			•
A description of the physical condition of the monument a			
See sheet two			
occ officer two			
			 -
SURVEYOR'S STATEMENT		ENSED LAND SUR	
			No.
This Corner Record was prepared by me or under my di		# . #/	
the Land Surveyors' Act on April 8,	•	★ Exp. 12 5241-9	в / >
Signed funda Caruthers L.S. or R.C.E. N	lumber705	3 No. 7053	
		* QE CALIFOR	
COUNTY SURVEYOR'S STATEM	ENT	PROFESS/ON	
his Corner Record was received APRIL 11	97		E)
4004	$\frac{1997}{4}$ and $\frac{6}{2}$	examined S	
and filed ATTAL 14 1997.		No. 26450 Exp. 3-31-840	E
signed form. Wooling Ti	tle Deput	C/VIL OF STATE OF STA	
County Survivordo Com		EAC CALLIS	,
County Surveyor's Comment			

A.P.N. 55-101-18