


CORNER RECORD

Document Number 058-321-06

City of Tiburon County of Marin, California

Brief Legal Description Lot 26 of 14 RM 25



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey _____
- Control
- Property
- Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found Standard Street Monuments & one original boundary corner (hub RCE 12510), and recent points marked as 5/8" rebars & Cap LS 7950.

A description of the physical condition of the monument as found and as set or reset:

Set one line point with 1/2 rebar & cap LS 5290

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on 7/21/15

Signed David Harp L.S. or R.C.E. Number LS 5290



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received November 25, 2015 and examined

and filed December 7, 2015

Signed Paul S. Sinst Title County Surveyor



County Surveyor's Comment _____

N. 0° 51' 02" W

100.001

29

4° 53' 21"

L: 38.83

L: 140.31

76.73

N. 61° 04' 30" E

L: 27.59, L: 175.17

L: 27.94

"Not to Scale"

2919.7

102.2

R: 430

Fed Std. Mon

649

202.30

Basis of Bearings - found pts

46.57

59.37

31.53

14.15

Fd 5/8" Bar LS 7950

Fd 5/8" Bar LS 7950

Set 1/2 Bar LS 5290

Fd Rvd. Hub RCE 12510

Fd 5/8" Bar LS 7950

R: 171

VENADO DRIVE

Fed Std Mon.

R: 225

R: 190

L: 100.61

L: 99.77

L: 100.61

L: 99.77

L: 100.61

L: 99.77

L: 100.61

L: 99.77

L: 100.61

L: 99.77

L: 100.61

L: 99.77

L: 100.61