


# CORNER RECORD

Document Number A.P.N. 59-071-62

City of TIBURON

County of MARIN, California

Brief Legal Description 32 Q.S. 50, DN. 95-011382 (BOTH MARIN CO. RECORDS)



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey JAN. 1996

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
FOUND REBAR & CAP LS 3887 AND FOUND NAIL, NO TAG, AS SHOWN  
ON 32 Q.S. 50 (PTS. A + B) WERE HELD FOR BASIS OF BEARINGS AT  
N 31° 59' 00" W.

A description of the physical condition of the monument as found and as set or reset: MONUMENTS SET ARE  
3/4" IRON PIPE W/ PLASTIC CAP "RCE 18221". REPLACED NAIL (PT B ABOVE)  
AND FOUND HUBS LS 2738 (5 TOTAL) W/ IRON PIPES. RE-ESTABLISHED  
2 CORNERS ALONG LINE OF BASIS OF BEARINGS, ALL AS SHOWN ON  
PAGE 2 OF 2, THIS CORNER RECORD.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on MAY 21 1997.

Signed Bruce A. Gowdy L.S. or R.C.E. Number LS 6725

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAY 27 1997 and examined and filed MAY 28 1997.

Signed John M. Woolley Title Deputy

County Surveyor's Comment \_\_\_\_\_

