


# CORNER RECORD

Document Number A.P.N. 64-204-19  
City of Sausalito County of Marin, California

Brief Legal Description Lot 38, Sausalito Land and Ferry Company 6 RM 16



### CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial


Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found 1/2" rebar tagged LS 5767 at the Southwest and Southeast  
corners of Lot 38.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_  
Set 3/4" iron pipe tagged RCE 18221 at the Northwest corner of Lot 38.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
the Land Surveyor's Act on AUGUST 29, 2001  
Signed [Signature] P.L.S. or R.C.E. No. 18221



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 31, 2001  
and examined and filed SEPTEMBER 4, 2001  
Signed [Signature] P.L.S. or R.C.E. No. 7128  
Title DEPUTY



County Surveyor's Comment \_\_\_\_\_