


CORNER RECORD

Document Number 64-204-35

City of Sausalito County of Marin, California

Brief Legal Description Lot 21 of 3 Maps 16



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
The monuments at the Southerly line of Lot 21 are the same as shown
on 29 O.S. 40. The monument at the Northwest corner of Lot 21 was found
as shown on the reverse of this page. The Northeast corner of Lot 21
was reset using measurements from the monuments found. (See map on reverse)

A description of the physical condition of the monument as found and as set or reset: _____
Southeast corner found in good condition. Southwest and Northwest
corners, nail holding tag rusted through, nail and tag replaced with
L.S. 5102. Northeast corner re-established as shown on reverse of this
page. (See map on reverse) Sausalito

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on January 15 1993.


Signed [Signature] L.S. or R.C.E. Number 5102 Exp. 6-95



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1-21 1993 and examined
 and filed 1-22 1993.

Signed [Signature] Title DCS



County Surveyor's Comment _____

