CORNE	RECOF	\	ndex <u>20-0</u>	
City of SAUSALITO	<u>_</u>			PN 064-335-14
oney or		_ ,		California
	OTTPORTION OF LOT 39	AS SHOWN IN VOLUM	IE IS AT PAGE (	S2 SHEET 4 OF 6 OF MAPS.
	CORNE	R TYPE		OINATES (Optional )
	Government Corner	Control		E
	Meander	Property X		
	Rancho	Other $\square$		U.S. Survey Foot
		Ш		Epoch Date
	Date of Survey 02-04	1-2019	Vertical Datum_	
				Public Resources Code 8801-881
			Complies with	Public Resources Code 8890-890
PLS Act Ref: ☐ 8765(d	) 🗌 8771	<b>X</b> 8773		Other:
Corner/ Left as	found Establishe	d Rebuilt		☐ Pre-Construction
Monument: Found of	and tagged 💢 Reestablis	hed Reference	ed	☐ Post-Construction
Narrative of corner identified and monument as found, set, reset, replaced, or removed:  See sheet #2 for description(s):  FOUND 2.5" BRASS DISC WITH PUNCH IN GOOD CONDITION STAMPED LS 3075 IN THE CENTER OF ARANA  CIRCLE AND LINCOLN DRIVE AS SHOWN ON MAP OF MARINA VISTA SUBDIVISION FILED IN VOLUME 13 OF  MAPS AT PAGE 62. SET 1/2" IRON PIPE IN SOUTHERLY CORNER OF LOT 39 AND 40 AND A 1 1/2" BRASS  DISC AND MAG NAIL IN THE TOP FACE OF CURB AT THE EXTENSION OF THE COMMON LINE TO SAID LOTS 39  AND 40 BOTH MONUMENTS TAGGED LS 9565 REEDER. SEE PAGE TWO FOR DETAILS.				
This Common December	SURVEYOR'S STATEME			_
This Corner Record was				1 AND S
the Professional Land Su	irveyors' Act on9	- 21	,2020	SED S W POPL
Signed	P.L.S. N			No L.S.9565
This Corner Record was	received FEBRUARY	11 , 2020		OF CALL
and examined and filed	10/14	, 2020		111445
Signed	P.L.S.	or R.C.E. No. 9	292	SIN R. SEMERAPA
Title DEPUT	J			(a) (a)
				0202 OH

APN: 064-335-14 HLS JOB #4357

Page 1 of 2

