	CORNER RECORD Document Number 72 - 191 - 08
<u> </u>	ity of VICINITY OF KENTFIELD County of MARIN, California
E	rief Legal Description 23 PM 53
	CORNER TYPE  Government Corner    Control    E
	Corner – Left as found □ Found and tagged □ Established ☑ Reestablished □ Rebuilt □
3	dentification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: $ESTABLISH$ $A$ $RANDCM$ $POINT$ $CN$ $THE$ $SOUTHERLY$ $LINE$
5	OF LOT 1 (23 PM) 53); SOUTHERLY LINE BEING THAT
Ž	COURSE 574°22'47" W, 441.15'. SAID KANDOM POINT
6	SET FROM FOUND POINTS OF 23 PM 53 AS DEPICTED UPON THE SKETCH UPON THE KEVERSE SIDE
ブ	and ly Mahare
`	A description of the physical condition of the monument as found and as set or reset: SEI REDAT WITH PLS CAP 5379 AFFIXED TO TOP & DRIVEN
ZÍ )	FLUSH WITH SULTOUNDING GRADE.
0,	7 60011 60611. 501. 501. 501.
3 3	
CRAIN TON SURVEYIN	SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on DECENBER 26 2000  Signed P.L.S or R.C.E. No. PLS 5379  PLS of CALFORD  FOR CALFORD
っ つ	COUNTY SURVEYOR'S STATEMENT
Z Z	This Corner Record was received JANUARY 4, 2007
D SK	and examined and filed February 7, 2007  Signed P.L.S or R.C.E. No. 7128  Title County Survey or Exp. 12-31-08 **  No. 7128
	County Surveyor's Comment

Borpels-1297 JN 10617 Page 1 of 2

