dentification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: The Northwest corner of Lot 158, a 3/4" ron pipe and tas LS 36/6, was found out of position by 0.66 feet this corner was reset in its original position. The North corner of Lot 150 was not found; this corner was reset its original position. Existing corners of Lot 159 s Lot 1 were vicated and verified by this surveyor set description of the physical condition of the monument as found and as set or reset: Both corners set are 1/2" iron pipes 30" and set or reset: Both corners set are 1/2" iron pipes 30" and set or reset: COUNTY SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on COUNTY SURVEYOR'S STATEMENT This Corner Record was received AUGUST 6, 2001 and examined and filed AUGUST 7, 2001 PLS OF R.G.E. No. 7128 PLS OF CHIEF. No. 7128 Signed PLS OF R.G.E. No. 7128	city of Uninc	Document Number _ orporated <u>APN 100-331-12</u> County of	100-331-12 1AR IN, Californi
Government Corner Control Record Nad27 NAD83 Nad27 NAD83 Nad27 NAD83 Nad27 NAD83 Nad28	Brief Legal Description	Lot 158 Oceana Marin Vi	nit 5 15 RM 11
SURVEYOR'S STATEMENT This Corner Record was received AUGUST 7, 2001 Signed PLS erricte. No. 7128 SIRVE PUTCH SIRVEYOR'S STATEMENT This Corner Record was received AUGUST 7, 2001 Signed PLS erricte. No. 7128 SIRVE PUTCH SIRVE PUTCH SIRVE PUTCH SIRVE PUTCH AUGUST 7, 2001 Signed PLS erricte. No. 7128 SIRVE PUTCH S	 +	Government Corner	NAD27
The northwest corner of Lot 158, a 3/4" ron pipe and tag LS 36/6, was Abund out of position by 0.66 feet this corner was reset in its original position. The North Corner of Lot 150 was not found; this corner was reset 175 original assistant. Existing corners of Lot 159 & Lot 175 original assistant. Existing corners of Lot 159 & Lot 189 & Lot 18	Corner – Left as	found Found and tagged Established Rees	tablished 🛛 Rebuilt 🗆
COUNTY SURVEYOR'S STATEMENT This Corner Record was receivedAUGUST 6, 2001 and examined and filedAUGUST 7, 2001 SignedP.L.S or R.C.E. No7128 TitlePEPUTO	Corner St Li 175 original re were located A description of the physic	as, ton. Existing corners of a cond verified by this surveyor al condition of the monument as found and as set or reset:	Lot 159 5 Lot 15 Soth corners set
COUNTY SURVEYOR'S STATEMENT This Corner Record was receivedAUGUST 6, 2001 and examined and filedAUGUST 7, 2001 SignedP.L.S or R.C.E. No7128 TitlePEPUTO		SURVEYOR'S STATEMENT	DIAND SURVEY
COUNTY SURVEYOR'S STATEMENT This Corner Record was receivedAUGUST_6, 2001 and examined and filedAUGUST_7, 2001 SignedP.L.S er R.C.E. No7128 TitleDEPUTY	This Corner Record was the Land Surveyor's Act o	prepared by me or under my direction in conformance with August 4 200/ Ruschney(P.L.S of R.C.E. No. 670Z	10.6702 R
Signed		•	SLANDS
County Surveyor's Comment	and examined and filed _	AUGUST 7, 2001	Exp. <u>i2/31/02</u> No. 7128
	Title <u>DEPUT</u>	<u> </u>	GA CALIT
			CALITY

