


CORNER RECORD

Document Number 141-304-07

City of Novato

County of MARIN, California

Brief Legal Description Lot 409, Map of Meyers Subdivision, 7 R.M. 86



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey _____

COORDINATES (Optional)

- N. _____
- E. _____
- Zone _____ NAD27 NAD83
- NAD83 Epoch _____
- Elev. _____
- Vert. Datum: NGVD29 NAVD88
- Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found Subdivision monuments per 7 R.M. 86


A description of the physical condition of the monument as found and as set or reset:
Set 3/4" IRON Pipes with county tags @ the SELY corners of Lot 409

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on June 19, 2006

Signed Michael A. Brogan P.L.S. or R.C.E. No. 25 5767

CHIEF OF SURVEYS, MARIN CO. OPW



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JULY 5, 2006

and examined and filed AUGUST 7, 2006

Signed _____ P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment _____

DIMENSIONS ARE IN FEET AND DECIMALS THEREOF

⊗ = FOUND SUBDIVISION MONUMENT PER 7 R.M. 86

