


CORNER RECORD

Document Number A.P. 176-251-54City of SAN ANSELMOCounty of MARIN, CaliforniaBrief Legal Description PARCEL 2 26 P.M. 29

CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey 12/20/01

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NAVD88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

REESTABLISHED THE PROPERTY CORNER
FROM WITNESS POINTS

A description of the physical condition of the monument as found and as set or reset: _____

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 12/20/01

Signed Lawrence P. Doyle P.L.S. or R.C.E. No. PLS 4694



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received 1-3-2002

and examined and filed 1-8-2002

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title DEPUTY

County Surveyor's Comment _____





TARRY ROAD

FOUND 3/4" PIPE
& PLUG L.S. 6234

PARCEL 1

26 P.M. 29

S09°03'45"W
198.94'

PARCEL 3

N86°57'35"W 133.00'

PARCEL 2

FOUND 3/4" PIPE & PLUG
WHICH WAS DESTROYED DURING
CONSTRUCTION AND REPLACED WITH
NAIL & TAG L.S. 4694 ON A.C. CURB.

N49°53'12"E
70.69'



CORNER RECORD
PARCEL 2 26 P.M. 29

SAN ANSELMO MARIN COUNTY CALIFORNIA

SCALE: 1" = 10'
DATE: 12/20/01
LAWRENCE P. DOYLE
LAND SURVEYOR/CIVIL ENGINEER

P.O. BOX 1609 MILL VALLEY CA 94942 (415-388-9585)

DRAWING NO.
594-98