


# CORNER RECORD

Document Number

A.P.N. 179-191  
A.P.N. 179-181  
A.P.N. 179-241/242

City of VICINITY OF LOS RANCHITOS County of MARIN, California

Brief Legal Description PORTION OF 205.116



## CORNER TYPE

Government Corner ☐ Control ☐  
Meander ☐ Property ☒  
Rancho ☐ Other ☐  
Date of Survey APRIL 4, 2005

## COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27 ☐ NAD83 ☐  
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29 ☐ NAVD88 ☐  
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

3/4" IRON PIPE WITH TAG RCE 3230 WAS STRADDLED &  
A STANDARD MONUMENT CASING WAS SET. THE IRON  
PIPE WAS NOT SURVEYED FOR ITS CURRENT POSITION.  
THIS WAS A JOINT EFFORT OF MARIN C.L.S.A. &  
MARIN COUNTY ROAD CREW. (SEE OVER)

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on APRIL 10 2005

Signed David Contreras P.L.S. or R.C.E. No. 5065



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 28, 2005

and examined and filed JULY 27, 2005

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

