

CORNER RECORD


Document Number 193.132.34

City of BOLINAS

County of MARIN

California

Brief Legal Description PARCEL A & B AS DEPICTED UPON 40550



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 7/22/98

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Reestablished the westerly line of the surveyed line of 40550. Reestablished from existing pipes set by this office along the easterly line of said 40550 in May 1998 of which a corner record is on file in the office of Marin County DPW

A description of the physical condition of the monument as found and as set or reset:

REFER TO SKETCH ON PAGE 2
Unless noted otherwise, set 1/2" rebar with PLS CAP 5379 AFFIXED TO TOP & DRIVEN flush with EXISTING GRADE

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on AUGUST 5th 19 98

Signed [Signature] L.S. or R.C.E. Number LS 5379
Renewal 6-30-00




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 17 19 98 and examined

and filed AUGUST 18 19 98

Signed [Signature] Title DEPUTY



County Surveyor's Comment _____

PREPARED BY: DJ SCRANTON SURVEYING NOVATO, CA

(JN 9841)

