

CORNER RECORD


Document Number A.P.N. 005-021-14

City of SAN ANSELMO

County of MARIN, California

Brief Legal Description LOT 28,

6 P.M. 88



CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 1-8-98

COORDINATES  
(Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- SEE OVER -

A description of the physical condition of the monument as found and as set or reset:

- SEE OVER -

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JAN. 23 19 98


Signed David Contreras or R.C.E. Number LS 5065



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 28 19 98 and examined and filed JANUARY 29, 98

Signed John M. Wooley Title Deputy



County Surveyor's Comment \_\_\_\_\_

⊙ = FD. 3/4" IRON PIPE MONUMENT @ SURFACE OF ASPHALT PAVING.

○ = SET 1/2" REBAR, CAP C.S. 5065

● = FD. NAIL & TAG @ TOP WALL

$R = 30'$   
 $\Delta = 33^\circ 34'$   
 $L = 17.58$

