CORNER RECORD Document Number APN 009-280-08 (ADT)

Brief Legal DescriptionC	enterline monument of Bel	llam Boulevard as	shown on Book 15 of M	laps at Page 3, M.C.R.
Mea	CORNER TYP vernment Corner ander ncho te of Survey July 30, 201	Control ☐ Property ☐ Other ☑	N. Not De E. NAD 83 Epoch CCS 83 Zone	VD29 □ NAVD88 □
Corner: Left as found □	Found and Tagged ☐	Established	Reestablished 🛚	Rebuilt 🗆
Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Original monument destroyed by construction activites without being referenced (RP'd). Found, confirmed by field measurement, and used street monuments shown on Book 15 of Maps at Page 33 and Book 20 at Page 81 to re-establish the centerline monument of Bellam Boulevard as shown on Sheet 2.				
Original monument destr	I condition of the monument a oyed by construction active a city standard monument w	ities and was not r		nent is a 2" brass disc
:	SURVEYOR'S STATEME			5
the Land Surveyor's Act on Signed	DUNTY SURVEYOR'S STAT Delived SEPTEMBER 20, 201/20.	20 <u>15</u> . or R.C.E. Number EMENT 2+ 20 1 5 and	LS 6421	EXP 12 31 14 EXP 12 31 14 ESONAL LAND SUBJECT SIMONITCH AT NO. 7821 AT THE OF CALIFORNIA

