


**CORNER RECORD**  
**San Rafael**

Document Number \_\_\_\_\_

City of \_\_\_\_\_ County of Marin, California

Brief Legal Description Lands of Geister as shown upon Book 18 of Surveys at Page 58



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 10 August 2011

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


Found 3/4" iron pipe with bronze nail (tag missing) per 18-Surveys-58; and Found 2" diameter brass disk stamped "F-2" and "F-3" as Basis of Bearings per 12-Surveys-27; and found bronze nail and tag "LS 3887" per Book 18 of Surveys, at page 58 on Canal Right-of-Way, being a reference point along the Canal R/W line, as shown upon reverse side.

A description of the physical condition of the monument as found and as set or reset: Set temporary construction points as described upon reverse side.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 10 August 2011

Signed [Signature] P.L.S or R.C.E. No. LS 4794  
4794



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received AUGUST 16, 2011  
and examined and filed SEPTEMBER 6, 2011

Signed [Signature] P.L.S or R.C.E. No. 7128  
Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_

