


CORNER RECORD

Document Number I.N. 2006-0008131

City of SAN RAFAEL

County of MARIN, California

Brief Legal Description PARCELS 1 & 2 BOOK 21 OF PARCEL MAPS AT PAGE 31, MARIN COUNTY RECORDS



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey _____

COORDINATES (Optional)

- N. _____
- E. _____
- Zone _____ NAD27 NAD83
- NAD83 Epoch _____
- Elev. _____
- Vert. Datum: NGVD29 NAVD88
- Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 3/4" I.D. iron pipe with plastic plug "L93775" per Book 21 of Parcel Maps, at Page 31; Marin County Records, as shown upon reverse side, (unless noted otherwise on reverse side).

A description of the physical condition of the monument as found and as set or reset:
As shown upon reverse side


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 2 June 2010.
Signed [Signature] P.L.S or P.C.E. No. 4794



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 16, 2010
and examined and filed JULY 20, 2010
Signed [Signature] P.L.S or P.C.E. No. 7128
Title COUNTY SURVEYOR



County Surveyor's Comment _____

LEGEND:

• Denotes found 3/4" Iron Pipe with plastic plug "LS 3775" per 21-PM-31, unless noted otherwise.

* JP Denotes Joint Utilities Pole

Found 5/8" rebar with plastic cap "PLS 7053" per 1998-M-61 22' off wire fence

1998-M-61

