


CORNER RECORD

Document Number 016-031-13

City of Vicinity San Rafael

County of MARIN, California

Brief Legal Description Subdivision Monuments of G RM 62



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Iron pipe subdivision monuments on MONCADA WAY
per G RM 62
referenced pipes, as shown on back, to rebuild
after planned repaving


A description of the physical condition of the monument as found and as set or reset:

See back

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on May 22 2014

Signed Michael A. Brogan P.L.S or R.C.E. No. LS 5767



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 16, 2014

and examined and filed JUNE 25, 2014

Signed Richard G. Simonitch P.L.S or R.C.E. No. 7821

Title DEPUTY



County Surveyor's Comment _____

● — FOUND IRON PIPE
 X — SET CUT X

6 RM 62



45

A.P.N
016-031-15

46

A.P.N
016-031-14

47

A.P.N
016-031-13

A.P.N
016-031-12

48

40

A.P.N
016-031-17

39

A.P.N
016-031-18

36

A.P.N
016-031-19

Reference Tie Line Table

Line #	Length	Direction
L1	28.18	N24° 19' 45"W
L2	37.73	N64° 36' 01"W
L3	105.68	S66° 41' 29"W
L4	50.32	S79° 13' 03"E
L5	142.55	N79° 52' 17"W
L6	104.80	S89° 26' 60"E

COUNTY OF MARIN
 DEPARTMENT OF PUBLIC WORKS
 SURVEY SECTION

SCALE: 1" = 80'

CORNER RECORD

