


CORNER RECORD

Document Number 38-322-17/18
City of TIBURON County of MARIN, California

Brief Legal Description LOT 7/8 14RM 22



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey JUNE 5 1997

COORDINATES
(Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
REESTABLISH REAR LOT CORNER COMMON TO LOTS 7/8 MAP OF
REEDLAND WOODS UNIT 2 (14RM 22) FROM EXISTING MONUMENTS OF
RECORD ON CORTE SAN FERNANDO.

A description of the physical condition of the monument as found and as set or reset:
SET 1/2" REBAR / PLS CAP 5379 "SCRANTON" AFFIXED TO TOP AND DRIVEN FLUSH
WITH NATURAL GRADE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors Act on JUNE 10 1997

Signed Douglas J. Scranton L.S. or R.C.E. Number PLS NO 5379
RENEWAL 6-30-2000



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 20 1997 and examined
and filed JUNE 23 1997.

Signed John M. Wooley Title Deputy



County Surveyor's Comment _____

DJ SCRANTON SURVING NOVATO, CA

JN 9029

FOUND 3/4" I.P.
PCE 11628

SCALE 1"=50'

LOT 9

38-322-18

LOT 8

30' STRIP OF LAND
D.N. 86-035680
(APN 38-322-16)

THIS CORNER
RECORD

STD. STREET
MONUMENT

R = 46.00'

LOT 7

Δ = 18°00'00"

L = 11.24'

S 39°00'00" W 137.65'

1A PM 22
REEDLAND WOODS UNIT 2

CORTE SAN FERNANDO

55'00"00" E 28.100'

N 39°00'00" E 28.000'

N 51°00'00" W 75.000'

38-351-16

LOT 6

S 39°00'00" W 136.02'

STD. STREET
MONUMENT

LOT 5

Δ = 6°28'14"
L = 75.06'

R = 664.64'

NOTE:

EASEMENTS NOT
SHOWN.