


**CORNER RECORD**

Document Number AP 39-141-01

City of TIBURON

County of MARIN, California

Brief Legal Description LOT 39 10 MAPS 53



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 6-07

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

RETRACEMENT OF 10 MAPS 53  
FOUND MONUMENTS AS SHOWN ON REVERSE.


A description of the physical condition of the monument as found and as set or reset:

SET 1/2" REBAR & CAP LS 6344

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 8-67

Signed [Signature] P.L.S or R.C.E. No. PLS 6344



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received NOVEMBER 19, 2007  
and examined and filed DECEMBER 17, 2007

Signed [Signature] P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment \_\_\_\_\_

