


CORNER RECORD

Document Number 39.271.26
City of TIBURON County of MARIN, California

Brief Legal Description 16 PM 96 PARCEL A



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 6/4/2007

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found ORIGINAL HUB @ NW CORNER OF
PARCEL A 16 PM 96 / Reset
with 1/2" rebar PLS 5379 CAP TO
Perpetuate LOCATION ~ see sketch on
Reverse side

A description of the physical condition of the monument as found and as set or reset:

set 1/2" rebar / PLS CAP 5379 AFFIXED TO TOP
& driven flush with surrounding
grade

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on June 19 2007

Signed [Signature] P.L.S or R.C.E. No. PLS 5379

COUNTY SURVEYOR'S STATEMENT


This Corner Record was received JUNE 21, 2007

and examined and filed JUNE 25, 2007

Signed [Signature] P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____



Vertical text on the left margin: REVISED BY: DOUG SCRANTON SURVEYING and Novato, CA