


CORNER RECORD

Document Number 049-063-17

City of Mill Valley

County of Marin, California

Brief Legal Description Lot 15 Tam Terrace 12 RM 36



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey March 4, 2008

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Retracement of 12 RM 36
Found Monuments as shown on reverse side.

A description of the physical condition of the monument as found and as set or reset: Set 1/2" Rebar & cap
LS 6344

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on March 4, 2008

Signed [Signature] P.L.S or R.C.E. No. PLS 6344

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MARCH 14, 2008

and examined and filed MARCH 19, 2008

Signed [Signature] P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____

