


CORNER RECORD

Document Number 50-026-12

City of MILL VALLEY

County of MARIN, California

Brief Legal Description LOT 16, BLOCK 302, MARIN TERRACES SUB. 3, 5 RM 29
APN 50-026-12



CORNER TYPE

COORDINATES
(Optional)

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Reset ANGLE POINT IN THE NORTHERLY LOT LINE OF LOT 16, BLOCK 302,
5 RM 29 AS SAID CORNER WAS REESTABLISHED UPON 24 05 82, (RECORD
OF SURVEY, MILL VALLEY LAND COMPANY). POINT RESET FROM EXISTING
STREET MONUMENTS ON VENTURA WAY & AS SHOWN UPON SAID RECORD
OF SURVEY (24 05 82)

A description of the physical condition of the monument as found and as set or reset:
set 1/2" rebar with PLS 5379 CAP Affixed to TOP

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on July 1st 19 94.


Signed Douglas J. Scranton L.S. or R.C.E. Number PLS 5379
License renewal 6-30-96



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 7-6 19 94 and examined
and filed 7-7 19 94.

Signed Robert Darrell Beaumont Title DCS



County Surveyor's Comment _____

Prepared by: DJ SCRANTON SURVEYING & OLIVE AVE. NOVATO, CA