


**CORNER RECORD**

Document Number APN 050-061-37,38

City of MILL VALLEY

County of MARIN, California

Brief Legal Description PARCEL 1, PARCEL MAP (10PM51)



**CORNER TYPE**

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey \_\_\_\_\_

**COORDINATES (Optional)**

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27  NAD83   
 NAD83 Epoch \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vert. Datum: NGVD29  NAVD88   
 Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
FOUND 3/4" I.P. & PLASTIC PLUG, RCE 12510 AS PER  
PARCEL MAP (10 PM 51).

A description of the physical condition of the monument as found and as set or reset: SET 3/4" I.P. w/  
PLASTIC PLUG, RCE 30465 AND SET GINNEY;  
SEE PAGE 2

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on NOV. 4<sup>th</sup> 2003

Signed [Signature] P.L.S. or R.C.E. No. 30465



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received NOVEMBER 6, 2003

and examined and filed NOVEMBER 14, 2003

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_