


CORNER RECORD

Document Number 051-044-05

City of MILL VALLEY and County of MARIN, California

Brief Legal Description: LOT 34, BLOCK 205 OF MAP ENTITLED "MAP OF MARIN TERRACE, SUBDIVISION NO. 2 MARIN HEIGHTS", FILED 6/16/1913 IN BOOK 4 OF MAPS AT PAGE 44, MARIN COUNTY OFFICIAL RECORDS.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other

Date of Survey 8/2/2016

COORDINATES (Optional)

N: _____
E: _____
Zone: _____ NAD 27 NAD 83
Elev: _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

CORNER - LEFT AS FOUND FOUND AND TAGGED ESTABLISHED REESTABLISHED REBUILT

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND MONUMENTS PER R2 AS SHOWN ON PAGE 2.

A description of the physical condition of the monument as found and as set or reset: _____

FOUND MONUMENTS AND SET POINTS AS SHOWN ON PAGE 2.

SURVEYOR'S STATEMENT:

The corner record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on SEPTEMBER 5 2016

Signed: Serena L. Goodwin L.S.# 8708



COUNTY SURVEYOR'S STATEMENT:

The corner record was received SEPTEMBER 28, 2016

and examined and filed OCTOBER 31, 2016

Signed: Richard G. Simonitch R.C.E. or L.S. No. 7821

Title: County Surveyor



COUNTY SURVEYOR'S COMMENT:

LEGEND

- SUBJECT BOUNDARY LINES PER R1,R2
- - - ADJOINER BOUNDARY LINES PER R1,R2
- FOUND 1/2" REBAR PER R2 OR AS NOTED
- FOUND 1/2" IRON PIPE PER R2
- SET 5/8" REBAR & PLASTIC CAP LS 8708
- R1 RECORD MAP: BOOK 4, PAGE 44
- R2 RECORD OF SURVEY: BOOK 26, PAGE 19

AMERICAN LAND SURVEYING, INC.
 1390 Market St, #303, San Francisco, Ca 94102
 P:(415) 888-8580 ALS16038 E:office@alspls.com

CORNER RECORD

