

CORNER RECORD


APN No. 051 - 083 - 45 (Optional)

Document Number 51-083-45

City of MILL VALLEY

County of MARIN, California

Brief Legal Description LOTS 33, 34, AND 35, BOOK 4 OF MAPS, PAGE 44



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey JUNE 7, 2000

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner - Left as found Found and tagged Established Reestablished Rebuilt

In compliance with Section 8771 of the Professional Land Surveyors' Act, this corner record is being filed to ESTABLISH ____ / REESTABLISH ____ the position of an existing monument PRIOR ____ / SUBSEQUENT ____ to street or highway reconstruction. (Use this portion only when applicable.)


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND POINTS AS SHOWN ON REVERSE.

A description of the physical condition of the monument as found and as set or reset:
SET CORNERS AS SHOWN ON REVERSE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JUNE 30, 2000.

Signed John C. Govers L.S. or R.C.E. Number R.C.E. 17923



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JULY 27, 2001 and examined and filed JULY 31, 2001.

Expiration 12-31-02
 Date: _____

Signed _____ Title Deputy County Surveyor

County Surveyor's Comment _____

