


**CORNER RECORD**

Document Number APN 051-233-01

City of MILL VALLEY

County of MARIN, California

Brief Legal Description APN 051-233-01, LOT 16 & 17 BLK 20, 4 R.M. 11



**CORNER TYPE**

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey \_\_\_\_\_

**COORDINATES (Optional)**

- N. \_\_\_\_\_
- E. \_\_\_\_\_
- Zone \_\_\_\_\_ NAD27  NAD83
- NAD83 Epoch \_\_\_\_\_
- Elev. \_\_\_\_\_
- Vert. Datum: NGVD29  NAVD88
- Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
FOUND EXISTING IRON PIPES PER 30 RS 59 AND 26 RS 73 USED TO REESTABLISH N/E CORNER OF APN 051-233-01. BASIS OF BEARINGS 30 RS 59.

A description of the physical condition of the monument as found and as set or reset: SET RIVET AND BRASS TAG IN RETAINING WALL AT N/E CORNER

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on DECEMBER 28 2004.  
Signed Michael E. Ford P.L.S. or R.C.E. No. 7237



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received SEPTEMBER 17, 2007  
and examined and filed OCTOBER 22, 2007  
Signed Craig Tackabery P.L.S. or R.C.E. No. 7128  
Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_