


**CORNER RECORD**

A.P.N.

Document Number 052-022-08  
County of MARIN, California

VICINITY City of TAMALPAIS VALLEY / MILL VALLEY

Brief Legal Description LOT 504 PER 7 R.M. 55



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 9-13-06

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


= SEE OVER =

A description of the physical condition of the monument as found and as set or reset:

= SEE OVER =

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JAN. 27 2007  
Signed David Contreras P.L.S. or R.C.E. No. 5065



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received FEBRUARY 8, 2007  
and examined and filed MARCH 7, 2007  
Signed \_\_\_\_\_ P.L.S. or R.C.E. No. 7128  
Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_