APN 052-042-37 Document Number 2009-0055559

CORNER RECORD

	ords, being Lot 424 of "Map of Kay Park Unit		
	Corner Type	Coor	dinates (optional)
	Government Corner □ Control □ Meander □ Property Rancho □ Other □ Date of Survey: March 19, 2015	N. E. Zone Elev.	Datum
Corner - Left as fou	and □ Found and tagged □ Established ☑	Reestablished □	Rebuilt □
or re-establish the and Startling Road monuments as show destroyed by consticlearly not original A description of the Set two 3/4" Iron P prolongation of the 4.00' westerly of the	type of corner found; Evidence used to iden corner: Found center line monuments per 7 M at Starling Court, and accepted as original and wn hereon, but monuments on Flamingo Rd at ruction. Found monuments on Flamingo Road and do not fit record position. Held record lot the physical condition of the monument as for the physical condition of the monument as for the contract and southerly property lines. Set one is southwest corner on the prolongation of the southwest of the northwesterly corner on the prolongation of the SURVEYOR'S STATEMENT	Iaps 55 on Flaming undisturbed. Search Cardinal Rd and Rd at Marin Ave and reposition as shown and and as set or a theast and southeast 2/4" Iron Pipe & Goutherly line. Set of the set of	to Rd at Starling Rd whed for original obin Rd are clearly northerly thereof are hereon. Teset: t corners on the Cap, PLS 7901, one 1/2" Rebar and
		6	
Signed Aaron R. Smith COU	UNTY SURVEYOR'S STATEMENT	AARON R. SMITH No. L7901	RICHARD G. SIMONITCH

