


# CORNER RECORD

Document Number 055-183-15

City of TIBURON County of MARIN, California

Brief Legal Description LANDS OF MARTINEZ, LOT 43 (8RM7) APN 055-183-15  
DN 95-054322



## CORNER TYPE

Government Corner ☐ Control ☐  
 Meander ☐ Property ☒  
 Rancho ☐ Other ☐  
 Date of Survey 06/08/2001

## COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

CORNERS SET AS PER 8RM7

BASIS OF BEARING ESTABLISHED USING TWO FOUND CENTER LINE STANDARD MONUMENTS  
ON HILARY DRIVE AS PER (13RM58). BOTH MONUMENTS WITH CAST IRON COVERS

A description of the physical condition of the monument as found and as set or reset:

1 SET REBAR

1 SET 3/4" IP RCE 30465

1 SET WOOD GUINEA

3 FOUND STANDARD MONUMENTS (STREET) WITH CAST IRON COVERS

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on JUNE 8<sup>th</sup> in 2001

Signed: [Signature] L.S. or R.C.E. Number RCE 30465



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JULY 23, 2001 and examined

and filed JULY 26, 2001

Signed: [Signature] Title DEPUTY



County Surveyor's Comment \_\_\_\_\_

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_