


CORNER RECORD

Document Number APN 58-231-15

City of Tiburon

County of Marin, California

Brief Legal Description Lot 52 /Marinero Residence NO. 1 10 RM 75, MCR



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey July 10, 1997

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Reestablish the two rear lot corners to Lot 52/ 10 RM 75. Set corners from existing street monuments shown per record map on Acela Drive.

A description of the physical condition of the monument as found and as set or reset: _____
Set one half inch rebar with plastic yellow cap affixed to top and embossed with "Scranton, PLS NO. 5379/ pipe driven flush with surrounding grade.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on July 18 19 97.

Signed Douglas J. Scranton L.S. or R.C.E. Number PLS NO. 5379 renewal 6/30/97



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JULY 21 19 97 and examined and filed JULY 22 19 97.

Signed John M. Woolley Title Deputy



County Surveyor's Comment _____

JN 9718

PREPARED BY: DJ SCRANTON SURVEYING 845 OLIVE AVE. NOVATO, CA 94945 897-2666