


CORNER RECORD

Document Number 3570-OR-113

City of Tiburon

County of Marin, California

Brief Legal Description Lot 22, "Map of El Marinero", Book 14 of Maps, at Page 25



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 27 September 2002

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Founda Standard Street monuments with nail and tag "RCE 12510" per 14-Maps-25, Marin County Records.

(A) Found 5/8" rebar with plastic cap "LS 7115"

(B) Found lead plug & tag "LS 4794" per corner record filed November 1999.

A description of the physical condition of the monument as found and as set or reset: _____

(C) Set hand-dewn redwood dowell with nail & tag "LS 4794"

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 14 October 2002

Signed [Signature] P.L.S or R.C.E. No. LS 4794



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCTOBER 10, 2002

and examined and filed OCTOBER 16, 2002

Signed [Signature] P.L.S or R.C.E. No. 7128

Title DEPUTY



County Surveyor's Comment _____