


CORNER RECORD

Document Number A.P. 058-341-05

City of TIBURON

County of MARIN, California

Brief Legal Description LOT 5 PER 14 R.M. 90



CORNER TYPE COORDINATES (Optional)

Government Corner Control
Meander Property
Rancho Other
Date of Survey 7/27/07

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND TWO REBARS/CAPS L.S. 7053 AND FOUND 1/2" REBAR/CAP AND SET CAP L.S. 4694 USING
FOUND STREET MONUMENTS ON MEADOWHILL DRIVE PER 14 R.M. 90 AND AS SHOWN ON SHEET 2.

A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on JULY 27 2007

Signed Lawrence P. Doyle P.L.S. or R.C.E. No. P.L.S. 4694



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 2, 2007

and examined and filed SEPTEMBER 5, 2007

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____

