


CORNER RECORD

Document Number AP 058-351-11

City of TIBURON

County of MARIN, California

Brief Legal Description LOT 53, 14 RM 94



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 7-21-99

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PLAT OF SURVEY PAGE 2 OF 2.

A description of the physical condition of the monument as found and as set or reset:

SEE PLAT OF SURVEY PAGE 2 OF 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on SEPTEMBER 14, 1999

Signed [Signature] P.L.S. or ~~_____~~ No. 6649



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 9-17-99

and examined and filed 9-20-99

Signed [Signature] P.L.S. or R.C.E. No. 26450

Title DEPUTY

County Surveyor's Comment _____

