


CORNER RECORD

Document Number A.P.# 059-012-07

City of TIBURON

County of MARIN, California

Brief Legal Description LOT 7 "BLOCK B" 2 O.S. 160



CORNER TYPE                      COORDINATES (Optional)

Government Corner       Control   
Meander                       Property   
Rancho                       Other

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27       NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum:      NGVD29       NAVD88   
Meas. Units:      Metric       Imperial

Date of Survey 4/26/04

Corner-    Left as found     Found and tagged     Established     Reestablished     Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

REESTABLISHED PROPERTY LINES FROM STREET MONUMENTS 2 O.S. 160


A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on APRIL 28 2004

Signed Lawrence P. Doyle      P.L.S. or R.C.E. No. P.L.S. 4694



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAY 10, 2004

and examined and filed JUNE 7, 2004

Signed [Signature]      P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_