


CORNER RECORD

Document Number A.P. # 59-061-29

City of TIBURON

County of MARIN, California

Brief Legal Description COMMON LINE PCL 2 & PCL 3, 2 PM 83



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 8/1/02

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FND 3/4" I.P.'S TAGGED P.L.S. 5296 AS SHOWN ON
33 OS 90 AND ON REVERSE

A description of the physical condition of the monument as found and as set or reset: SET 3/4" I.P. AND
TAG P.L.S. 5296 AS SHOWN ON REVERSE.

AP # 059-061-29


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on AUGUST 1, 2002
Signed [Signature] P.L.S or R.C.E. No. PLS 5296



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 21, 2002
and examined and filed AUGUST 23, 2002
Signed [Signature] P.L.S or R.C.E. No. 7128
Title DEPUTY



County Surveyor's Comment _____