


**CORNER RECORD**

Document Number APN 059-193-21

City of TIBURON

County of MARIN, California

Brief Legal Description PARCEL B, PARCEL MAP, MINOR SUBD (1PM74)



**CORNER TYPE**

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey \_\_\_\_\_

**COORDINATES (Optional)**

- N. \_\_\_\_\_
- E. \_\_\_\_\_
- Zone \_\_\_\_\_ NAD27  NAD83
- NAD83 Epoch \_\_\_\_\_
- Elev. \_\_\_\_\_
- Vert. Datum: NGVD29  NAVD88
- Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
FOUND 3/4" IP AND FOUND SCREW & TAG, RCE 12510  
AS PER 22 PM 78

A description of the physical condition of the monument as found and as set or reset:  
SET 3/4" IP & PLASTIC CAP, RCE 30465; AND SET  
2" X 2" WOOD HUB & TACK; SEE PAGE 2

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 7/17/03  
Signed [Signature] P.L.S. or R.C.E. No. 30465



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received JULY 21, 2003  
and examined and filed JULY 29, 2003  
Signed [Signature] P.L.S. or R.C.E. No. 7128  
Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_