



JERRICO ASSOCIATES

SUITE 27  
77 MARK DRIVE  
SAN RAFAEL, CA 94903

7061


# CORNER RECORD

Document Number 104-170-11

City of Tomaes Bay

County of Marin, California

Brief Legal Description 2570 OR 546 (914 OR 96)



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey Dec 30, 1993

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Points found established by 13 PM 70

(A) Found pipe and LS 2535

(B) Found hub and LS 2535

A description of the physical condition of the monument as found and as set or reset:

(C) Found hub and LS 2535 disturbed by tree root (set nail and LS 3887 in  
 (D) Found hub and LS 2535 disturbed. Reset rebar & LS 3887 cap. root)

(E) Set rebar & LS 3887 cap.

(F) Set rebar & LS 3887 cap.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
 the Land Surveyors' Act on December 30 1993.

Signed [Signature] L.S. or R.C.E. Number LS 3887

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received January 4 1994 and examined  
 and filed 1-4 1994.

Signed [Signature] Title DUS

County Surveyor's Comment \_\_\_\_\_

