


CORNER RECORD

Document Number 100.680.07

City of NOVATO

County of MARIN, California

Brief Legal Description LOT 67, MARIN GOLF & COUNTRY CLUB ESTATES, Unit 2, 19M58



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey Oct. 10, 2001

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

REESTABLISH THE WESTERLY LINE OF LOT 67, MARIN GOLF & COUNTRY CLUB ESTATES, Unit 2, 19 MAPS 58, FROM EXISTING STREET MONUMENTS OF RECORD ON THUNDERBIRD DRIVE & AS OUTLINED ON SKETCH ON REVERSE SIDE.

A description of the physical condition of the monument as found and as set or reset:

set 1/2" rebar with pls cap along said westerly line (being a curved line with a radius of 140 feet) at miscellaneous intervals (refer to sketch on reverse side). Also set lot line point @ THUNDERBIRD DRIVE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on October 18 2001

Signed Douglas J. Scanton P.L.S. or R.C.E. No. PLS 5379
renewal 6.30.2004



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCTOBER 22, 2001

and examined and filed OCTOBER 24, 2001

Signed _____ P.L.S. or R.C.E. No. 7128

Title DEPUTY



County Surveyor's Comment _____

Prepared by: DJ SCANTON SURVEYING 845 OLIVE AVE NOVATO, CA

